




# Kestrel 5700 is showing that Sig 5K or 10K Laser Rangefinder is “Locked” and cannot connect




To fix this, connect the LRF to the Sig App



Then go to Settings



Change Rangefinder mode from BDX-E to BDX-X



Then reconnect with the Kestrel 5700